


State of Utah

DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director



Inspection Report Minerals Regulatory Program

Report Date: November 24, 2004

Mine Name: Red Warrior	Permit number: S/053/012			
Operator or Permittee Name:	Inspecti	on Date: N	ovember 15, 2	004
L&M General Engineering & Construction, Inc.				
Permittee Mailing Address:				
756 Dixie Drive, P.O. Box 898				
St. George, Utah 84771				
	Weathe	r: Clear, Co	ol	
Inspector(s): Doug Jensen	Inspection Start Time: 3:45 PM			
	Inspection End Time: 4:45 PM			
Other Participants: None	Site location/Area Inspected (i.e. Pit #):			
	Quarry			
Permit Status: Inactive	Surface Ownership: SITLA			
Current Acreages: <5 acres	Mineral Ownership: SITLA			
Total Permitted (Bonded): <5 acres	Mineral Mined: Limestone			
Total Disturbed: ~3.75 acres	Type of Mine: Quarry			
Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds				
2. Public Safety (open shafts, adits, trash,	\bowtie			
signs, highwalls)				
3. Protection of Drainages				
4. Explosives, magazines				
5. Deleterious Material				
6. Roads (maintenance, surfacing, dust control,				
safety)				
7. Concurrent Reclamation				
8. Erosion Control				
9. Demolition				
10. Backfilling and Grading (trenches, pits,				
roads, highwalls, shafts, drill holes)				
11. Water Impoundments				
12. Soils				
13. Revegetation				
14. Air Quality				
15. Other				



Inspection Date: November 15, 2004; Report Date: November 24, 2004

Page 2 of 2 S/053/012

Purpose of Inspection:

This site has not been inspected for some time and there has not been any documentation of the total disturbance at the site.

Inspection Summary:

The site has not changed since my last visit to the site. There is no sign of any recent mining activity or removal of quarried material.

Highwalls appear to be stable with no apparent failures.

Waste material has been place in a ephemeral drainage at the site but has not caused any problems with runoff to date.

There are not apparent piles of soil harvested from the disturbed area before mining. Pictures were taken of the site and are included in this report.

Directions to the site:

Travel 1.2 miles from the summit of Utah Hill, turn right and travel 1.8 miles to the entrance road to the quarry. The quarry lies .2 miles up this road.

Date: November 24, 2004

GPS data:

The site was GPS'd, but to date no map has been produced from the data. The map will be generated at a later date.

Inspector's Signature

dj:jb

Enclosures: photos

cc: Jerry Lewis, L&M General Engineering & Construction, Inc.

John Blake, SITLA

O:\M053-Washington\S0530012-RedWarrior\inspections\ins-11152004.doc

